

3-32

Obtain the response of a linear oscillator to a step function and to an impulse function (in the limit  $\tau \rightarrow 0$ ) for overdamping. Sketch the response functions.